



<u>II II II</u> II PRIIIR ART



<u>IIII</u>I PRIDR ART



MCI 4

QCI 4

REDUCTANT
(e.g. Na OR Mg METAL)

EXOTHERMIC REACTION TO
PRODUCE Q/M ALLOY.

